



The contained information in this handbook are only informative and they can being change without warning and they must not being understandings with some engagement from Promax srl. Promax srl does not assume responsibility or obligates for errors or inaccuracies that can be found in this handbook. Except how much granted from the license, no part of this publication can be reproduced, saved in a recording system or transmitted in whatever form or with any means, electronic, mechanical or recording system or otherwise without Promax srl authorization.

Any reference to names of society or products have only demonstrative scope and it does not allude to some real organization.

Rev. 2.0.2

1 PREFACE

This manual describes the VTB application for IsoNs software. The VTB application is the same for the IsoNs Windows Xp,7,8 and IsoNs Windwos CE

2 BASE COMPONENTS

To begin the application, is necessary to insert the following components in a new VTB Application:

2.1 Select Hardware

Tools \rightarrow Options \rightarrow Hardware conf. (Ex NG35)

Option		Σ
General RS232 Protocol Field Bus Protocol	Hardware Conf.	Connection
Target Hardware NG35 FrameWork Create Framework component	Saving memory reserve Length block: 256 N.blocks per Recipe1 N.Recipes: 1 Tot. mem. IMS: 3	ed area x x = 256 bytes
	ок	Annulla

2.2 Insert Object cobjinterpola

Objects \rightarrow *Motor Control* \rightarrow *cobjinterpola.vco*



You can also insert the Obj interpola Rampe S

The difference is that in this object you can use the ISONS Parameter JERK, sinus acceleration ramps.



Properties setting of objinterpola 2.3

nome (name)	\rightarrow
N. Assi (Number of Axes)	\rightarrow
N.tratti (depth look ahead)	\rightarrow
Vper	\rightarrow
Div. Vper	\rightarrow
Abilita Arcto	\rightarrow

- objinterpola1 (default)
- Number of interpolated axes for this process
- Look Ahead depth Default 16
- Not change
 - Not change
 - Not change

Interpola 1				
Property Events				
Property	Value			
Nome	Interpola 1			
Left	130			
Тор	75			
N.assi	3			
N.tratti	16			
Vper	1024			
Div. Vper	1024			
Abilita arcto	1			

Max DEPTH look ahead (this value must be multiple of 2 ex: 8 – 16 – 32 etc.)

NGQuark

NG35

2 Axes \rightarrow 3 Axes \rightarrow 4 Axes \rightarrow NGM EVO 2 Axes \rightarrow 3 Axes \rightarrow 4 Axes \rightarrow

 $AII \rightarrow 2048$

2.4 **Insert Object Iso Virtual**

Objects → *IsoNs* → - *ISOVirtual* - \$Rev 2.3.0 (*ISOVirtual* - \$Rev 1.1.9 *is Obsolete*) The ISOVirtual light is used for NGQ or NGQx system only This component uses little memory



Properties setting of IsoVirtual 2.5

.

nome (name) Indice processo Parametri Custom (Curtom Parameter)

.

- ISOV1 (default) \rightarrow
- \rightarrow Not change
- \rightarrow See below

IS0V1	
Property Even	ts
Property	Value
Nome	ISOV1
Left	95
Тор	35
Indice processo	1
Parametri custom	0

2.6 Insert a long fixed variable name fixed0

This variable is used to synchronized the IsoNs PC process

Objects → Fixed Var



Select the first address (click in the 0 position)

Addr	Variable	Туре	
0			
1			

Press Add Button

Addr	Variable	Туре
0	fixed0	LONG
1	***********************	**********************
2	************************	***********************
3	***********************	**********************

3 Insert the Axes type

After insert the base components, is possible insert the axes

Choose the axes type

 $\mathsf{Objects} \rightarrow \mathsf{IsoNs} \rightarrow \mathsf{IsoCanOpen}$

Axes Type

IsoCanOpen

This contain all the CanOpen Driver Typical set

AX1			
Property Events			
Property	Value		
Nome	AX1		
Left	90		
Тор	175		
Nodo	1		
Indice asse ISO	0		
Nome processo	ISOV1		
Nome quota pdo	qi		
Mask Allarmi	0xFFFFFFFF		
Mask Parametri	0x00		

Nome(Name)

Nodo (Node)	\rightarrow
Indice Asse Iso (Index ISO Axis)	\rightarrow
Nome Processo (process Name)	\rightarrow
Nome quota pdo (PDO CanOpen Name)	\rightarrow

Axis Name

 \rightarrow \rightarrow

 \rightarrow

- CanOpen Node
- Indicates the ISONS Axis (0 -X, 1-Y, 2 Z etc.)
- Process Name with is associate ISOVIRTUAL OBJECT
- PDO CanOpen Name for interpolation mode

IsoPid.vco

This contain all the Analog driver +/- 10V with encoder loop Driver, closed loop for Stepper motor and CanOpen (with external encoder)

IsoPid- NG35 Filtro Digitale



Used for analog motor with +/-10 V and encoder for closed loop only for NG35 and NGIO expansion **Properties**

Nome(Name)	\rightarrow Object IsoPid name	
Indice Asse Iso (Index ISO Axis)	ightarrow Indicates the ISO Axis (0 -X , 1-Y , 2 – Z etc.)	
Nome Processo (process Name)	ightarrow Process Name with is associate ISOVIRTUAL OBJECT	
Indice Asse NGIO (Index NGIO Axis)	ightarrow Indicates the channel of NGIO with is connect the driver	
	0 \rightarrow Ch0 of First NGIO	
	1 \rightarrow Ch1 of First NGIO	
	2 \rightarrow Ch0 of Second NGIO	
	3 \rightarrow Ch1 of second NGIO etc.	
Kp,Ki,Kv,Err Saturazione,Divisore,Dir	ightarrow PID Parameters set by IsoNs PC application	
Enable Kp,Ki,Kd	\rightarrow Not change (True)	
T0 Level	\rightarrow Level of encoder index	
	0 Low	
	1 High	
Soglia ServoErr, Ritardo ServoErr	ightarrow Parameters set by IsoNs PC application	

NGPP- *NG-PP + PID*



Used for closed loop in STEPPER MOTOR. Normally this object is used for high precision axes



Properties

Nome(Name)	\rightarrow Object IsoPid name
Indice Asse Iso (Index ISO Axis)	\rightarrow Indicates the ISO Axis (0 -X , 1-Y , 2 – Z etc.)
Nome Processo (process Name)	\rightarrow Process Name with is associate ISOVIRTUAL OBJECT
Indice Asse NGPP (Index NGPP Axis)	ightarrow Indicates the channel of NGPP with is connect the driver
· · · · ·	0 \rightarrow Ch0 of First NGPP
	1 \rightarrow Ch1 of First NGPP
	2 \rightarrow Ch2 of First NGPP
	3 \rightarrow Ch3 of First NGPP
	4 \rightarrow Ch0 of Second NGPP
	5 \rightarrow Ch1 of Second NGPP Etc
Indice Asse NGIO (Index NGIO Axis)	ightarrow Indicates the encoder channel input relative to axis
	0 \rightarrow Ch0 of First NGIO
	1 \rightarrow Ch1 of First NGIO
	2 \rightarrow Ch0 of Second NGIO
	3 \rightarrow Ch1 of second NGIO etc.
Kp,Ki,Kv,Err Saturazione,Divisore,Dir	ightarrow PID Parameters set by IsoNs PC application
Enable Kp,Ki,Kd	\rightarrow not change (True)
T0 Level	\rightarrow Level of encoder index
	0 Low
	1 High
Soglia ServoErr,Ritardo ServoErr	\rightarrow Parameters set by IsoNs PC application
Max Freq, Scalav, Enable Out	\rightarrow Reserved

IsoDouble_Enc.vco

This contain all the Iso CanOpen with external encoder closed loop

CanOpen + PID

Used for external closed loop in CanOpen ESTUN DRIVES with interpolation mode. Normally this object is used for high precision axes





Properties

Nome(Name) Nodo(Node) Indice Asse Iso (Index ISO NS Axis) Nome Processo (process Name) Nome quota pdo (PDO CanOpen Name) Indice Asse NGIO (Index NGIO Axis)

- \rightarrow Object IsoPid name
- \rightarrow Driver Canopen Node
- \rightarrow Indicates the ISO NS Axis (0 -X , 1-Y , 2 Z etc.)
- \rightarrow Process Name with is associate ISOVIRTUAL OBJECT
- \rightarrow PDO CanOpen Name for interpolation mode
- \rightarrow Indicates the encoder channel input relative to axis
 - 0 \rightarrow Ch0 of First NGIO
 - 1 \rightarrow Ch1 of First NGIO
 - 2 \rightarrow Ch0 of Second NGIO
 - 3 \rightarrow Ch1 of second NGIO etc.
- \rightarrow PID Parameters set by IsoNs PC application
- \rightarrow Not change (True)
 - \rightarrow Level of encoder index
 - 0 Low
 - 1 High
 - \rightarrow Parameters set by IsoNs PC application
 - \rightarrow Delay in Millisecond for home commando (typically 1000)

Kp,Ki,Kv,Err Saturazione,Divisore,Dir Enable Kp,Ki,Kd T0 Level

Soglia ServoErr,Ritardo ServoErr Home Delay

IsoPP.vco

This contain all the Axes STEP DIR open loop

IsoPP NGM EVO Passo-Passo

Used for the NGM EVO board and STEP DIR axes



Properties

Nome(Name) Indice Asse Iso (Index ISONS Axis) Nome Processo (process Name) NGM EVO Channel \rightarrow Object IsoPid name

3

- \rightarrow Indicates the ISONS Axis (0 -X , 1-Y , 2 Z etc.)
- \rightarrow Process Name with is associate ISOVIRTUAL OBJECT
- \rightarrow Indicates the channel of NGM EVO with is connect the driver
 - $\begin{array}{ccc} 0 & \rightarrow & Ch0 \\ 1 & \rightarrow & Ch1 \end{array}$
 - $2 \rightarrow Ch2$
 - \rightarrow Ch3

IsoPP NG35 (NG-PP) Passo-Passo

Used for the NG35+NGPP board and STEP DIR axes



Properties

Nome(Name) Indice Asse Iso (Index ISONS Axis) Nome Processo (process Name) NG-PP Channel

- \rightarrow Object IsoPid name
- \rightarrow Indicates the ISONS Axis (0 -X , 1-Y , 2 Z etc.)
- → Process Name with is associate ISOVIRTUAL OBJECT
- \rightarrow Indicates the channel of NGPP with is connect the driver
 - $0 \rightarrow Ch0 \text{ first NGPP}$
 - 1 \rightarrow Ch1 first NGPP
 - 2 \rightarrow Ch2 first NGPP
 - 3 \rightarrow Ch3 first NGPP
 - 4 \rightarrow Ch0 second NGPP
 - 5 \rightarrow Ch1 second NGPP etc.

IsoPP_slave.vco

This contain all the Axes STEP DIR open loop slave mode.

In this mode, the master can control the slave axes step dir connect at a board via CanOpen Ex:

NG35 Master NGQ Slave CanOpen with step axes

IsoPP_slave (Do not Use NGM13)

Used for the NGQ board and STEP DIR axes in canopen



Pro

Properti	les (a)	
	Nome(Name)	→ Object IsoPid name
	Indice Asse Iso (Index ISONS Axis)	\rightarrow Indicates the ISONS Axis (0 -X , 1-Y , 2 – Z etc.)
	Nome Processo (process Name)	\rightarrow Process Name with is associate ISOVIRTUAL OBJECT
	NGM-13 Channel	ightarrow Indicates the channel of NGQ with is connect the driver
		$0 \rightarrow Ch0$
		$1 \rightarrow Ch1$
		$2 \rightarrow Ch2$
		$3 \rightarrow Ch3$
	Nodo(Node)	\rightarrow NGO CanOpen node
	Nome quota pdo (PDO CanOpen Name)	\rightarrow PDO CanOpen Name for interpolation mode
/ In	sort the L/O	
When th	ne all axes are inserted, is possible insert the	additional I/O module
Choose	e the I/O type	
Objects	→ IsoNs → IsoCanOpen	
Iso-IO.	VCO	
	This contain all the I/O module	
	lso-IO – NG-IO - NGM-IO	
	I/O on the NGIO -NGMIO (NG35 -NGM EVO	expansion)
r.		expansiony
L	120 120	
Properti	es	
	Nome(Name)	\rightarrow Object IsoPid name
	Nome Processo (process Name)	\rightarrow Process Name with is associate ISOVIRTUAL OBJECT
	Indice ISO-IO (16 bit) (ISO-IO INDEX)	\rightarrow Number of block I/O from 0 to 15
		0 \rightarrow Group 1 - I/O from 0 to 15
		1 \rightarrow Group 2 - I/O from 16 to 31
		3 \rightarrow Group 3 – I/O from 32 to 47 etc.
	Indice NG-IO (NG-IO Index)	\rightarrow Indicates the number NGIO oer NGMIO expansion
	· · · · · ·	$0 \rightarrow$ First NGIO-NGMIO on local bus
		1 \rightarrow Second NGIO-NGMIO on local bus
		2 \rightarrow Third NGIO-NGMIO on local bus Etc
	Hardware enable	\rightarrow Do not change (true)
	That Gware enable	
	Iso-IO - CAN-IO – CAN-AX - NGM-13 SLAVE	
	I/O on the NGQ or NGQx slave CanOpen	
	CAN-IO CAN-AX	
Properti	ies	
	Nome(Name)	\rightarrow Object IsoPid name
	Nodo(Node)	\rightarrow NGO - NGOX -NGM EVOs CanOpen pode
	Allarma cfg (CEG Alarm)	\rightarrow Number of alarm generated when the board is in error
	Alarine eig (ei e Alarin)	default 11
		If you have more boards NCO NCOY NCM EVOs instrasso
		this value (42.42 etc)
		LINS VALUE (42,43 ELC)
	Nome Processo (process Name)	→ Process Name with is associate ISOVIRTUAL OBJECT
	indice ISO-IO (16 bit) (ISO-IO INDEX)	\rightarrow Number of block I/O from 0 to 15
		$0 \rightarrow$ Group 1 - I/O from 0 to 15
		1 \rightarrow Group 2 - I/O from 16 to 31
		$3 \rightarrow$ Group $3 - I/O$ from 32 to 47 etc.
	Hardware enable	ightarrow Do not change (true)
	Variabile Inp (Variable digital inputs PDO)	ightarrow Name for PDO digital inputs
	Variabile Out (Variable digital outputs PDO)	ightarrow Name for PDO digital outputs

CAN-PPN,- EMC-IO Do not use obsolete

5 USE the M functions to internal the CNC

In this example the ISO VIRTUAL OBJECT NAME is ISOV1

1) Set the VTB pointer at function ISOV1_start_m Insert the code in INIT TASK PLC

TASK PLC Code			
Ind L	ask PLC	Task PLC	
1	ISOV1	start_m=	start_macro
2			_

Start_macro is a function located in Main \rightarrow Page Functions This function is called automatically when the **M** function is invoked by PC

' start macro Function

```
·_____
```

function start_macro() as void

ISOV1_M_ack=1 ' set acknoleged for ISONS PC

select ISOV1_M_cmd case 1

' M Function 1

case 2 ' M Function 2

case 3

' M Function 3

case else

ISOV1_M_ack=0 ' M not found

endselect endfunction

5.1 **Read the M parameters**

IsoNs can write the M parameters from code:

IsoNs Code

\$_PARM1=100 \$_PARM2=130 M5

You can read in the VTB application this parameters in the following variables: $ISOV1_M_1 \rightarrow \$PARM1 ISOV1_M_2 \rightarrow \$PARM2$ $ISOV1_M_3 \rightarrow \$_PARM3 ISOV1_M_4 \rightarrow \$_PARM4$ ISOV1 M 5 \rightarrow \$ PARM5 ISOV1 M 6 \rightarrow \$ PARM6 $ISOV1_M_7 \rightarrow \$_PARM7 ISOV1_M_8 \rightarrow \$_PARM8$ $ISOV1_M_9 \rightarrow \$PARM9 ISOV1_M_10 \rightarrow \$PARM10$

VTB Code

```
function start_macro() as void
        ISOV1_M_ack=1 ' set acknoleged for ISONS PC
        select ISOV1_M_cmd
                case 5
```

' M Function 5 if ISOV1_M_1=100 && ISOV1_M_2=130

endif

ISOV1_status_m_run=0 ' Free the IsoNs application

case else

ISOV1_M_ack=0 ' M not found

endselect

endfunction

5.2 Write the M parameters

The VTB application can be write the M parameters for IsoNs application:

.....

IsoNs Code

M5

```
IF$ PARM1=100
```

. . .

•••

END IF

VTB Code

```
function start_macro() as void
        ISOV1 M ack=1 ' set acknoleged for ISONS PC
```

select ISOV1 M cmd

case 5

```
' M Function 5
ISOV1 M 1=100
```

ISOV1_status_m_run=0 ' Free the IsoNs application

```
case else
```

```
ISOV1_M_ack=0 ' M not found
```

endselect endfunction

5.3 M flags In the VTB application, the M functions have the following flags:

ISOV1_M_ack	If set True (1) indicate to IsoNs PC application the M is performed If set False (0) the M is not found – Error
ISOV1_M_cmd	Contains the M number invoked by IsoNs PC application
ISOV1_status_m_run	The IsoNs Part Program PC applications, wait for this flag to value False (0) The value True (1) lock the part program When the time out is reached, an error is performed
ISOV1_status_m_stop	This flag is set True (1) from IsoNs when the STOP REQUEST is performed The VTB application must stop all internal M cycles in run and reset this flag

5.4 Example M3 M4 M5 start/stop Spindle

The IsoNs application can be write the spindle speed (S function) automatically in the VTB variable **ISOV1_generic(9)** (only if the IsoNs PC parameter **WR_SPD9**=1) When in the Gcode is present the Function S **value**, automatically value is written in the **ISOV1_generic(9)** VTB array The following sample refers to NG35 with NGIO for analog Spindle output

Note:

MAXDAC is a VTB define 2047 (Dac division) MAXSPEEDSPINDLE is a VTB define the Rpm max of Spindle ex: 24000 CwOut is a bit of digital output for set the spindle in Cw mode CCwOut is a bit of digital output for set the spindle in CCw mode SpindleStart is a bit of digital output for Start Spindle VelSpindle is a VTB long variable

IsoNs Code S1200 // set to 1200 rpm M3 // start spindle in CW mode

VTB Code

function Start_Macro() as	s char	
ISOV1_m_ACK=1		
select ISOV1 M	cmd	
case 3 '	start spindle in CW	
	Cw=true' set Cw mode	
	Ccw= <mark>false</mark>	
	' calculate the Speed	
	VelSpindle=(ISOV1_gener	ic(9)*MAXDAC)/MAXSPEEDSPINDLE
	ng_dac(0,VelSpindle)	' Update the Speed on Dac out
	SpindleStart=true	' Start spindle
	ISOV1_status_m_run=0	
case 4 '	start spindle in CCW	
	Cw=false	
	Ccw=true ' set CCw mode	2
	' calculate the Speed	
	VelSpindle=(ISOV1_gener	ic(9)*MAXDAC)/MAXSPEEDSPINDLE
	<pre>ng_dac(0,VelSpindle)</pre>	' Update the Speed on Dac out
	SpindleStart=true	' Start spindle
	ISOV1_status_m_run=0	
case 5	' Stop spindle	
	SpindleStart=false	' Stop spindle
	VelSpindle=0	' set Speed to 0
	<pre>ng_dac(0,VelSpindle)</pre>	' Update the Speed on Dac out
	ISOV1_status_m_run=0	
case els	е	
	ISOV1_m_ACK=0	
endselect		

endfunction

6 Standard I/O

The following describes all virtual I/O exchange between VTB and application PC (the process is named ISOV1)

I/O	VTB VARIABLE	DESCRIPTION
External RUN request	ISOV1_ext_run	This variable is set True (1) the PLC cycle request the RUN to IsoNs application. Ex: when external RUN button is pressed if input_ext_run = 1 && ISOV1_status_run=0 ' test external input run and not in run ' request of run IsoNs PC application ISOV1_ext_run=1 ' the PC read this flag and RUN the part program endif
External STOP request	ISOV1_ext_stop	This variable is set True (1) the PLC cycle request the STOP to IsoNs application. Ex: when external STOP button is pressed if input_ext_stop = 1 && ISOV1_status_run=1 ' test external input stop and in run ' request of stop IsoNs PC application ISOV1_ext_stop=1 ' the PC read this flag and STOP the part program endif
External PAUSE request	ISOV1_ext_pausa	This variable is set True (1) the PLC cycle request the PAUSE to IsoNs application. Ex: when external PAUSE button is pressed if input_ext_pausa = 1 && ISOV1_status_pausa=0 ' test external input pause and in not in pause ' request of pause IsoNs PC application ISOV1_ext_pausa=1 ' the PC read this flag and PAUSE the part program endif
Negative limit switch for X axis	ISOV1_ext_fcm_x	Copy in this bit the digital input where is connected the Negative limit switch for X axis. ISOV1_ext_fcm_x=InputLimtXneg Automatically the VTB application stops the PartProgram
Positive limit switch for X axis	ISOV1_ext_fcp_x	Copy in this bit the digital input where is connected the Positive limit switch for X axis. ISOV1_ext_fcp_x=InputLimtXpos Automatically the VTB application stops the PartProgram
Negative limit switch for Y axis	ISOV1_ext_fcm_y	Copy in this bit the digital input where is connected the Negative limit switch for Y axis. ISOV1_ext_fcm_y=InputLimtYneg Automatically the VTB application stops the PartProgram

		Copy in this bit the digital input where is connected the Positive limit switch for Y axis.
Positive limit switch for Y axis	ISOV1_ext_fcp_y	ISOV1_ext_fcp_y=InputLimtYpos
		Automatically the VTB application stops the PartProgram
		Copy in this bit the digital input where is connected the Negative limit switch for Z axis.
switch for Z axis	ISOV1_ext_fcm_z	ISOV1_ext_fcm_z=InputLimtzneg
		Automatically the VTB application stops the PartProgram
De siti de l'asit		Copy in this bit the digital input where is connected the Positive limit switch for Z axis.
switch for Z axis	ISOV1_ext_fcp_z	ISOV1_ext_fcp_z=InputLimtZpos
		Automatically the VTB application stops the PartProgram
		Copy in this bit the digital input where is connected the Negative limit switch for A axis.
Negative limit switch for A axis	ISOV1_ext_fcm_a	ISOV1_ext_fcm_a=InputLimtAneg
		Automatically the VTB application stops the PartProgram
		Copy in this bit the digital input where is connected the Positive limit switch for A axis.
Positive limit	ISOV/1 ext fcn a	
switch for A axis		ISOV1_ext_fcp_a=InputLimtApos
switch for A axis	150V1_EXt_ltp_a	ISOV1_ext_fcp_a=InputLimtApos Automatically the VTB application stops the PartProgram
switch for A axis	150V1_EXt_ltp_a	ISOV1_ext_fcp_a=InputLimtApos Automatically the VTB application stops the PartProgram Copy in this bit the digital input where is connected the Negative limit switch for B axis.
switch for A axis Negative limit switch for B axis	ISOV1_ext_fcm_b	ISOV1_ext_fcp_a=InputLimtApos Automatically the VTB application stops the PartProgram Copy in this bit the digital input where is connected the Negative limit switch for B axis. ISOV1_ext_fcm_b=InputLimtBneg
switch for A axis Negative limit switch for B axis	ISOV1_ext_fcm_b	ISOV1_ext_fcp_a=InputLimtApos Automatically the VTB application stops the PartProgram Copy in this bit the digital input where is connected the Negative limit switch for B axis. ISOV1_ext_fcm_b=InputLimtBneg Automatically the VTB application stops the PartProgram
switch for A axis Negative limit switch for B axis	ISOV1_ext_fcm_b	ISOV1_ext_fcp_a=InputLimtApos Automatically the VTB application stops the PartProgram Copy in this bit the digital input where is connected the Negative limit switch for B axis. ISOV1_ext_fcm_b=InputLimtBneg Automatically the VTB application stops the PartProgram Copy in this bit the digital input where is connected the Positive limit switch for B axis.
switch for A axis Negative limit switch for B axis Positive limit switch for B axis	ISOV1_ext_fcm_b	ISOV1_ext_fcp_a=InputLimtApos Automatically the VTB application stops the PartProgram Copy in this bit the digital input where is connected the Negative limit switch for B axis. ISOV1_ext_fcm_b=InputLimtBneg Automatically the VTB application stops the PartProgram Copy in this bit the digital input where is connected the Positive limit switch for B axis. ISOV1_ext_fcp_b=InputLimtBneg Automatically the VTB application stops the PartProgram Copy in this bit the digital input where is connected the Positive limit switch for B axis. ISOV1_ext_fcp_b=InputLimtBpos
switch for A axis Negative limit switch for B axis Positive limit switch for B axis	ISOV1_ext_fcm_b	ISOV1_ext_fcp_a=InputLimtAposAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Negative limit switch for B axis.ISOV1_ext_fcm_b=InputLimtBnegAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Positive limit switch for B axis.ISOV1_ext_fcp_b=InputLimtBnegAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Positive limit switch for B axis.ISOV1_ext_fcp_b=InputLimtBposAutomatically the VTB application stops the PartProgram
switch for A axis Negative limit switch for B axis Positive limit switch for B axis	ISOV1_ext_fcm_b	ISOV1_ext_fcp_a=InputLimtAposAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Negative limit switch for B axis.ISOV1_ext_fcm_b=InputLimtBnegAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Positive limit switch for B axis.ISOV1_ext_fcp_b=InputLimtBnegAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Positive limit switch for B axis.ISOV1_ext_fcp_b=InputLimtBposAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Negative limit switch for C axis.
switch for A axis Negative limit switch for B axis Positive limit switch for B axis Negative limit switch for C axis	ISOV1_ext_fcm_b	ISOV1_ext_fcp_a=InputLimtAposAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Negative limit switch for B axis.ISOV1_ext_fcm_b=InputLimtBnegAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Positive limit switch for B axis.ISOV1_ext_fcp_b=InputLimtBposAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Negative limit switch for B axis.ISOV1_ext_fcp_b=InputLimtBposAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Negative limit switch for C axis.ISOV1_ext_fcm_c=InputLimtCneg
switch for A axis Negative limit switch for B axis Positive limit switch for B axis Negative limit switch for C axis	ISOV1_ext_fcm_b	ISOV1_ext_fcp_a=InputLimtAposAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Negative limit switch for B axis.ISOV1_ext_fcm_b=InputLimtBnegAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Positive limit switch for B axis.ISOV1_ext_fcp_b=InputLimtBnegAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Positive limit switch for B axis.ISOV1_ext_fcp_b=InputLimtBposAutomatically the VTB application stops the PartProgramCopy in this bit the digital input where is connected the Negative limit switch for C axis.ISOV1_ext_fcm_c=InputLimtCnegAutomatically the VTB application stops the PartProgram
switch for A axis Negative limit switch for B axis Positive limit switch for B axis Negative limit switch for C axis	ISOV1_ext_fcm_b	ISOV1_ext_fcp_a=InputLimtApos Automatically the VTB application stops the PartProgram Copy in this bit the digital input where is connected the Negative limit switch for B axis. ISOV1_ext_fcm_b=InputLimtBneg Automatically the VTB application stops the PartProgram Copy in this bit the digital input where is connected the Positive limit switch for B axis. ISOV1_ext_fcp_b=InputLimtBpos Automatically the VTB application stops the PartProgram Copy in this bit the digital input where is connected the Negative limit switch for C axis. ISOV1_ext_fcm_c=InputLimtCneg Automatically the VTB application stops the PartProgram

		Copy in this bit the digital input where is connected the Positive limit switch for C axis.
\Positive limit switch for C axis	ISOV1_ext_fcp_c	ISOV1_ext_fcp_c=InputLimtCpos
		Automatically the VTB application stops the PartProgram
Negative limit		Copy in this bit the digital input where is connected the Negative limit switch for U axis.
switch for U axis	ISOV1_ext_fcm_u	ISOV1_ext_fcm_u=InputLimtUneg
		Automatically the VTB application stops the PartProgram
Desitive limit		Copy in this bit the digital input where is connected the Positive limit switch for U axis.
switch for U axis	ISOV1_ext_fcp_u	ISOV1_ext_fcp_u=InputLimtUpos
		Automatically the VTB application stops the PartProgram
		Copy in this bit the digital input where is connected the Negative limit switch for V axis.
switch for V axis	ISOV1_ext_fcm_v	ISOV1_ext_fcm_v=InputLimtVneg
		Automatically the VTB application stops the PartProgram
De siti ve live it		Copy in this bit the digital input where is connected the Positive limit switch for V axis.
switch for V axis	ISOV1_ext_fcp_v	ISOV1_ext_fcp_v=InputLimtVpos
		Automatically the VTB application stops the PartProgram
Negative limit		Copy in this bit the digital input where is connected the Negative limit switch for W axis.
switch for W axis	ISOV1_ext_fcm_w	ISOV1_ext_fcm_w=InputLimtwneg
		Automatically the VTB application stops the PartProgram
Positive limit		Copy in this bit the digital input where is connected the Positive limit switch for W axis.
switch for W axis	ISOV1_ext_fcp_w	ISOV1_ext_fcp_w=InputLimtWpos
		Automatically the VTB application stops the PartProgram
A = 7		Copy in this bit the digital input where is connected the sensor fro acqusitions G102 function
Acq Sensor	ISOV1_ext_acq	ISOV1_ext_acq=InputAcq
		Automatically the VTB application stops the Axes when the input is set

Stop Axes	ISOV1_stop_assi	When this bit is set, the Gcode application is stopped This bit is alternative to ISOV1_ext_stop for example can be used for forcing stop axes by external events if InputForceStop = 1 && ISOV1_status_run=1 ' Force a Stop axes ISOV1_stop_assi=1 ' the PC part program is stopped endif
Stop Axes with emergency	ISOV1_stop_emcy	When this bit is set, the Gcode application is stopped and ALARM EMERGENCY is invoked All drives are dissbled if InputForceEmcy = 1 && ISOV1_status_run=1 'Force a Stop axes with EMCY ISOV1_stop_EMCY=1 'the PC part program is stopped with error invoked endif
Emergency	ISOV1 ext emov	Copy in this bit the digital input where is connected the Emergency general output (typical N.C.)
Input	130V1_ext_emicy	Automatically the VTB application stops the PartProgram and a Alarm is invoked
Manual JOG X -	ISOV1_ext_jogm_x	Copy in this bit the digital input where is connected the External Jog X - Button ISOV1_ext_jogm_x=JogExtXm
		The Axis is moved in NEGATIVE direction at VJOG set by IsoNs application
Manual JOG X +	ISOV1_ext_jogp_x	Copy in this bit the digital input where is connected the External Jog X + Button ISOV1_ext_jogp_x=JogExtXp
		The Axis is moved in POSITIVE direction at VJOG set by IsoNs application
Manual		Copy in this bit the digital input where is connected the External Jog Y - Button
JOG Y -	ISOV1_ext_jogm_y	ISOV1_ext_jogm_y=JogExtYm
		The Axis is moved in NEGATIVE direction at VJOG set by IsoNs application
Manual	1601/4	Copy in this bit the digital input where is connected the External Jog Y + Button
JOG Y +	ISOV1_ext_jogp_y	ISOV1_ext_jogp_y=JogExtYp The Axis is moved in POSITIVE direction at VJOG set by IsoNs application
		Copy in this bit the digital input where is connected the External Jog Z - Button
Manual JOG Z -	ISOV1_ext_jogm_z	ISOV1_ext_jogm_z=JogExtZm
		The Axis is moved in NEGATIVE direction at VJOG set by IsoNs application

		Copy in this bit the digital input where is connected the External Jog Z + Button
Manual JOG Z +	ISOV1_ext_jogp_z	ISOV1_ext_jogp_z=JogExtZp
		The Axis is moved in POSITIVE direction at VJOG set by IsoNs application
		Copy in this bit the digital input where is connected the External Jog A - Button
Manual JOG A -	ISOV1_ext_jogm_a	ISOV1_ext_jogm_a=JogExtAm
		The Axis is moved in NEGATIVE direction at VJOG set by IsoNs application
		Copy in this bit the digital input where is connected the External Jog A + Button
Manual JOG A +	ISOV1_ext_jogp_a	ISOV1_ext_jogp_a=JogExtAp
		The Axis is moved in POSITIVE direction at VJOG set by IsoNs application
		Copy in this bit the digital input where is connected the External Jog B - Button
Manual JOG B -	ISOV1_ext_jogm_b	ISOV1_ext_jogm_b=JogExtBm
		The Axis is moved in NEGATIVE direction at VJOG set by IsoNs application
		Copy in this bit the digital input where is connected the External Jog B + Button
Manual JOG B +	ISOV1_ext_jogp_b	ISOV1_ext_jogp_b=JogExtBp
		The Axis is moved in POSITIVE direction at VJOG set by IsoNs application
		Copy in this bit the digital input where is connected the External Jog C - Button
Manual JOG C -	ISOV1_ext_jogm_c	ISOV1_ext_jogm_c=JogExtCm
		The Axis is moved in NEGATIVE direction at VJOG set by IsoNs application
		Copy in this bit the digital input where is connected the External Jog C + Button
Manual JOG C +	ISOV1_ext_jogp_c	ISOV1_ext_jogp_c=JogExtCp
		The Axis is moved in POSITIVE direction at VJOG set by IsoNs application
Manual		Copy in this bit the digital input where is connected the External Jog U - Button
JOG U -	ISOV1_ext_jogm_u	ISOV1_ext_jogm_u=JogExtUm
		The Axis is moved in NEGATIVE direction at VJOG set by IsoNs application
		Copy in this bit the digital input where is connected the External Jog U +
Manual JOG U +	ISOV1_ext_jogp_u	ISOV1_ext_jogp_u=JogExtUp
		The Axis is moved in POSITIVE direction at VJOG set by IsoNs application

Switch		This bit is used when the command axis home is performed
Homing X	ISOV1_ext_fcz_x	Copy in this bit the digital input where is connected the Homing X Switch ISOV1_ext_fcz_x=InputHoming_X
Manual JOG + Generic Axis	ISOV1_ext_jogp	The axis is set in the VTB variable ISOV1_asse_man (see above). Copy the input jog button ISOV1_ext_jogp=JogExtP
Manual JOG - Generic Axis	ISOV1_ext_jogm	The axis is set in the VTB variable ISOV1_asse_man. Copy the input jog button ISOV1_ext_jogm=JogExtM ISOV1_asse_man=0 \rightarrow X axis is set ISOV1_asse_man=1 \rightarrow Y axis is set ISOV1_asse_man=2 \rightarrow Z axis is set ISOV1_asse_man=3 \rightarrow A axis is set ISOV1_asse_man=4 \rightarrow B axis is set ISOV1_asse_man=5 \rightarrow C axis is set ISOV1_asse_man=6 \rightarrow U axis is set ISOV1_asse_man=7 \rightarrow V axis is set ISOV1_asse_man=8 \rightarrow W axis is set
Manual JOG W +	ISOV1_ext_jogp_w	Copy in this bit the digital input where is connected the External Jog W + Button ISOV1_ext_jogp_w=JogExtWp The Axis is moved in POSITIVE direction at VJOG set by IsoNs application This bit is used to move in manual mode possible direction a generic axis
Manual JOG W -	ISOV1_ext_jogm_w	Copy in this bit the digital input where is connected the External Jog W - Button ISOV1_ext_jogm_w=JogExtWm The Axis is moved in NEGATIVE direction at VJOG set by IsoNs application
Manual JOG V +	ISOV1_ext_jogp_v	Copy in this bit the digital input where is connected the External Jog V + Button ISOV1_ext_jogp_v=JogExtVp The Axis is moved in POSITIVE direction at VJOG set by IsoNs application
Manual JOG V -	ISOV1_ext_jogm_v	Copy in this bit the digital input where is connected the External Jog V - Button ISOV1_ext_jogm_v=JogExtVm The Axis is moved in NEGATIVE direction at VJOG set by IsoNs application

		Copy in this bit the digital input where is connected the Homing Y Switch
Homing Y Switch	ISOV1_ext_fcz_y	ISOV1_ext_fcz_y=InputHoming_Y
		This bit is used when the command axis home is performed
		Copy in this bit the digital input where is connected the Homing Z Switch
Homing Z Switch	ISOV1_ext_fcz_z	ISOV1_ext_fcz_z=InputHoming_Z
		This bit is used when the command axis home is performed
		Copy in this bit the digital input where is connected the Homing A Switch
Homing A Switch	ISOV1_ext_fcz_a	ISOV1_ext_fcz_a=InputHoming_A
		This bit is used when the command axis home is performed
		Copy in this bit the digital input where is connected the Homing B Switch
Homing B Switch	ISOV1_ext_fcz_b	ISOV1_ext_fcz_b=InputHoming_B
		This bit is used when the command axis home is performed
		Copy in this bit the digital input where is connected the Homing C Switch
Homing C Switch	ISOV1_ext_fcz_c	ISOV1_ext_fcz_c=InputHoming_C
		This bit is used when the command axis home is performed
		Copy in this bit the digital input where is connected the Homing U Switch
Homing U Switch	ISOV1_ext_fcz_u	ISOV1_ext_fcz_u=InputHoming_U
		This bit is used when the command axis home is performed
		Copy in this bit the digital input where is connected the Homing V Switch
Homing V Switch	ISOV1_ext_fcz_v	ISOV1_ext_fcz_v=InputHoming_V
		This bit is used when the command axis home is performed
		Copy in this bit the digital input where is connected the Homing W Switch
Homing W Switch	ISOV1_ext_fcz_W	ISOV1_ext_fcz_w=InputHoming_W
		This bit is used when the command axis home is performed

7 Status Word

The VTB application uses a Status Word for communicate to PC application the status. Normally this status is set by internal VTB functions, but the application can read the status. This Status Word is Bit mapped

VTB Bit Name	DESCRIPTION	
ISOV1_status_run	Setted to True (1) when the IsoNs application run the GCODE	
ISOV1_status_move	Setted to True (1) when the axes are in movements	
ISOV1_status_pausa	Setted to True (1) when the IsoNs application is in PAUSE MODE	
ISOV1_status_error	Setted to True (1) when the Alarm is present (EMCY drives, Emergency button etc.)	
ISOV1_status_rzero	Setted to True (1) when one axis is during search homing Home command by IsoNs application	
ISOV1_status_rsens	Setted to True (1) when the acquisition command is performed set to False (0) when the acquisition is finished G102 function by IsoNs application	
ISOV1_status_para_upd	Setted to True (1) when the PC application updates the VTB internal parameters. This flag is not reset automatically, but when read, you can reset. In the some case is necessary when the PC updates the VTB parameters, perform the operations with the new parameters.	
ISOV1_status_m_run	Setted to True (1) when the M cycle is in execution. Reset by M functions management, <i>See chapter 5 - "USE the M functions to internal the CNC"</i>	
ISOV1_status_m_stop	This flag is Setted True (1) from IsoNs when the STOP REQUEST is performed The VTB application must stop all internal M cycles in run and reset this flag	
ISOV1_status_home_x		
ISOV1_status_home_y		
ISOV1_status_home_z		
ISOV1_status_home_a		
ISOV1_status_home_b	This flag is Setted True (1) when the relative axis has performed the homing procedure	
ISOV1_status_home_c		
ISOV1_status_home_u		
ISOV1_status_home_v		
ISOV1_status_home_W		
ISOV1_status_enable_x		
ISOV1_status_enable_y		
ISOV1_status_enable_z		
ISOV1_status_enable_a		
ISOV1_status_enable_b	This flag is Setted True (1) when the relative axis is enabled or False if is Disabled	
ISOV1_status_enable_c		
ISOV1_status_enable_u		
ISOV1_status_enable_v		
ISOV1_status_enable_w		

8 PLC I/O management

The VTB application can use the PLC I/O in very simple mode. First, is necessary, load in the application the relative I/O object (**See chapter 4** - **"Insert the I/O"**) The VTB application use e definition Bit to management the I/O. The max number of I/O is:

256 Digital Inputs 256 Digital outputs

The I/O are a blocks of 16 bit

If is used the NGQ-NGQx module with 11 digital Inputs, you can not use the Inputs 11 to 15 (or relative to block 27 to 31 etc.) because these are not present in the board NGQ-NGQx You can not use the outputs 8 to 15 (or relative to block 24 to 31 etc)

If is used the NGIO-NGMIO module with 14 digital Outputs, you can not use the Outputs 14,15 (or relative to block 30,31 etc) because these are not present in the board NGIO-NGMIO

You can use always the outputs 14,15 for internal flag

8.1 Defined bit digital Inputs

ISOV1.inp0	\rightarrow Digital Inputs 1
ISOV1.inp1	→ Digital Inputs 2
ISOV1.inp2	→ Digital Inputs 3

ISOV1.inp255 → Digital Inputs 255

8.2 Defined bit digital Outputs

ISOV1.out0	→ Digital Outputs 1
ISOV1.out1	→ Digital Outputs 2
ISOV1.out2	→ Digital Outputs 3

ISOV1.out255 → Digital Outputs 255

Ex:

```
if ISOV1.inp0 = 1 && ISOV1.inp1=0
ISOV1.out0=true 'set out 0
```

endif

9 FEED External Override

By VTB application is possible management a potentiometer for Axes feed control. The potentiometer must be connected at analog input. The Variable is : ISOV1_vper

The value range is 0 to 1024, you can copy the analog input directly in this variable

Ex: The analog input is Number 1 Insert this code in main cycle or task plc cycle

ISOV1_vper=ng_adc(0)

If is used the NGM EVO,NGQ,NGQx analog inputs (12 bit – range from 0 to 4095) divide by 4 the ISOV1_vper ISOV1_vper=ng_adc(0) ISOV1_vper=ISOV1_vper/4

10 Electronic HandWheel

This chapter describe the management Electronic HandWheel.



VTB Example

The system is NG35+NGIO with following connection:

Variable used:

EncHandWheel	\rightarrow	Long
OutEnc	\rightarrow	Long
Input	\rightarrow	Long

Insert the Object FiltroVol in Main and set the parameters : *Objects→Motor Control→CFiltrovol.vco*



		1
FiltroVol1		-
Property Ever	nts	
Property	Value	-
Nome	FiltroVol 1	
Left	10	
Тор	10	
Numero elementi	10	
Molt. filtro	100	
Encoder	EncHandWheel	
Variabile	OutEnc	

Insert the following code in Init Task Plc: ISOV1_soft_sel_man=0 'Enable the internal VTB selector FiltroVol1.enable=1 'Enable filter

Insert the following code in Task Plc:

' Read the HandWheel Encoder,

۱<u>....</u>

<u>ا__</u>

' Put in EncHandWheel Variable

' Note: the () set the pointer - Very important

ng_enc(0,EncHandWheel())

```
'------

'Set the multiplier

'------

if ISOV1.inp3 'multiplier x1

ISOV1_msofv=1

endif

if ISOV1.inp4 'multiplier x10

ISOV1_msofv=10

endif

if ISOV1.inp5 'multiplier x100

ISOV1_msofv=100

endif
```

'Set the Axis

if ISOV1.	inp0	'Axis X
	ISOVI_asse_man	=0
endif		
if ISOV1.	inp1	'Axis Y
	ISOV1_asse_man	=1
endif		
if ISOV1.	inp2	'Axis Z
	ISOV1_asse_man	=2
endif		

'------'Update the Handwheel from FiltroVol Object

'______if !ISOV1_status_run FiltroVol1.enable=true ISOV1_qvola=OutEnc else FiltroVol1.enable=false ISOV1_qvola=0 endif

'Update the Jog Input

ISOV1_ext_jogp=ISOV1.inp6 ISOV1_ext_jogm=ISOV1.inp7

11 Machine Parameters

With VTB application you can read and write the machine Parameters.

Generally this function is not necessary, because the machine parameters are managed from IsoNs VTB application system, but if you want read or write the parameters this is possible.

All parameters are in the array **ISOV1_PARA**

The array dimension depends of Axes number. All parameters are type LONG (32 bit signed)

ISOV1_PARA array organization

0-49 General Parameters	50-99 Axis X Parameters	100-149 Axis Y Parameters	
-------------------------	-------------------------	---------------------------	--

11.1 General Parameters

Idx ISOV1_Para	Name	Description
0	VRIPOS	Axes Velocity repositioning after Pause (if in IsoNs is not present the Macro GOPAUSE)
1	SGLP	Threshold Edge
2	SGLR	Threshold of Arc error
3	ACQ_MODE	Acquisition type 0 → Speed 1 → step by step
4	ACQ_VEL	Feed Acquisition
5	ACQ_STEP	Step length for acquisition type 1
6	ACQ_TIME	Time for acquisition type 1
7	ACC_QSTOP	Acceleration for Quick stop
8	JERK	Jerk acceleration
9	NOSHORT	Remove the short linee
Free 10 to 49		

11.2 Axes X Parameters (50 x blocks)

Idx ISOV1_Para	Name	Description	
50	VJOG	JOG Feed Axis (mm/min)	
51	ACC_JOG	Acceleration JOG Axis (count)	
52	LIMITE_N_	Negative Software Limit Axis	
53	LIMITE_P_	Positive Software Limit Axis	
54	DSOFV	Jog Handwheel Divisor Axis	
55	RZERO_MODE	Homing mode	
56	RZERO_OFFSET	Homing Offset	
57	RZERO_PRESET	Homing Preset	
58	RZERO_VEL	Homing High Feed Axis	
59	RZERO_VELF	Homing Low Feed Axis	
60	RZERO_ACC	Homing Acceleration Axis	
61	MSOF	Number Count/Revolution Axis	
62	DSOF	Distance for One Revolution Encoder Axis	
63	GANTRY	Gantry Axis	
64	SGL_3D	Edge Threshold Axis 3D	
65	BACKSLASH	Axis Backslash (um)	
66	66 TBCK Axis Time Backslash (TAU)		
67	TSHF	Speed Shift	
Free 67 to 79			
	The following Parameters are present only for analog +/- 10V drives		
80	PID_KP	(Proportional Costant) Axis	
81	PID_KI	(Integral Costant) Axis	
82	PID_KV	(Feed Costant) Axis	
83	83 PID_I_LIMIT IL (Integration Limit) Axis		
84	PID_DIV	PID Magnitude Axis	
85	PID_SERVO	Servo Error Axis (um)	
86	PID_TIME_SERVO	During Time Servo Error Axis	
87	PID_DIR	Analog Direction Axis	
88	PID_OFFS_ANA	Analog Digital Offset Axis	
Free 88 to 99		······	
100 to 149 Axis Y parameters			
150 to 199 Axis Z parameters (if present)			
200 to 249 Axis A parameters (if present)			
250 to 299 Axis B parameters (if present)			
300 to 349 Axis C parameters (if present)			
350 to 399 Axis U parameters (if present)			
400 to 449 Axis V parameters (if present)			
450 to 499 Axis W parameters (if present)			

11.3 Custom Parameters

With IsoNs PC Application is possible declare a Custom machine Parameters. This parameters can be read by VTB application.

First is necessary declare in the Object ISOVIRTUAL (ISOV1) the MAX NUMBER OF CUSTOM PARAMETERS in the application.



The Custom parameters are available at the following address:

```
ISOV1_PARA(ISOV1_P_CUSTOM)
```

Where **ISOV1_P_CUSTOM** is a define automatically calculate by VTB compiler At this address is present the first custom parameter configured: the second is present in **ISOV1_PARA(ISOV1_P_CUSTOM+1) etc.** The real value is:

ISOV1_P_CUSTOM =50 * Axes Number + 50

Ex: 4 Axes configured and 3 custom parameters

	CUSTOM_1	Custom parameter 1	100
	CUSTOM_2	Custom parameter 2	100
	CUSTOM_3	Custom parameter 3	100
IF			

The CUSTOM_1 must have Address 250 The CUSTOM_2 must have Address 251 The CUSTOM_3 must have Address 252

CustomPar1=ISOV1_PARA(ISOV1_P_CUSTOM) CustomPar2=ISOV1_PARA(ISOV1_P_CUSTOM+1) CustomPar3=ISOV1_PARA(ISOV1_P_CUSTOM+2)

12 Alarms bit mapped

All alarms are bit mapped. If the application, sect the relative bit, the alarm is activated. Generally these alarms are activated by system IsoNs VTB automatically when the event is occurred. The application can read and write the single bit.

Bit Name	Alarm Description
ISOV1.allarm0	X Negative Limit Reached
ISOV1.allarm1	X Positive Limit Reached
ISOV1.allarm2	Y Negative Limit Reached
ISOV1.allarm3	Y Positive Limit Reached
ISOV1.allarm4	Z Negative Limit Reached
ISOV1.allarm5	Z Positive Limit Reached
ISOV1.allarm6	A Negative Limit Reached
ISOV1.allarm7	A Positive Limit Reached
ISOV1.allarm8	B Negative Limit Reached
ISOV1.allarm9	B Positive Limit Reached
ISOV1.allarm10	C Negative Limit Reached
ISOV1.allarm11	C Positive Limit Reached
ISOV1.allarm12	U Negative Limit Reached
ISOV1.allarm13	U Positive Limit Reached
ISOV1.allarm14	V Negative Limit Reached
ISOV1.allarm15	V Positive Limit Reached
ISOV1.allarm16	W Negative Limit Reached
ISOV1.allarm17	W Positive Limit Reached
ISOV1.allarm18	X SERVO-EMERGENCY
ISOV1.allarm19	Y SERVO-EMERGENCY
ISOV1.allarm20	Z SERVO-EMERGENCY
ISOV1.allarm21	A SERVO-EMERGENCY
ISOV1.allarm22	B SERVO-EMERGENCY
ISOV1.allarm23	C SERVO-EMERGENCY
ISOV1.allarm24	U SERVO-EMERGENCY
ISOV1.allarm25	V SERVO-EMERGENCY
ISOV1.allarm26	W SERVO-
ISOV1.allarm27	General EMERGENCY Activated
ISOV1.allarm28	Acquisition Error
ISOV1.allarm29	Short line found (active if the NO_SHORT=2)
ISOV1.allarm30	Free
ISOV1.allarm31	Free
ISOV1.allarm32	X Axis Configuration error (CanOpen or Ethercat)

ISOV1.allarm32	Y Axis Configuration error (CanOpen or Ethercat)
ISOV1.allarm34	Z Axis Configuration error (CanOpen or Ethercat)
ISOV1.allarm35	A Axis Configuration error (CanOpen or Ethercat)
ISOV1.allarm36	B Axis Configuration error (CanOpen or Ethercat)
ISOV1.allarm37	C Axis Configuration error (CanOpen or Ethercat)
ISOV1.allarm38	U Axis Configuration error (CanOpen or Ethercat)
ISOV1.allarm39	V Axis Configuration error (CanOpen or Ethercat)
ISOV1.allarm40	W Axis Configuration error (CanOpen or Ethercat)
ISOV1.allarm41	Free
ISOV1.allarm42	Free
ISOV1.allarm255	Free

13 CanOpen Alarms

The management of Canopen alarms (EMCY-OBJ), is performed directly by Axis object loaded. When the alarm is present, the single bit is set:

X SERVO-EMERGENCY

Y SERVO-EMERGENCY

Y SERVO-EMERGENCY

etc

In the ISOV1_last_allarm(node axis) you can find the CanOpen Code error

14 Examples

Following VTB application examples

14.1 NGQ-NGM EVO 3 Axes Step/Dir

Link RS32 on COM1 NGQ-NGM EVO

Digital Inputs

Digital Input 1	→ Switch Home X (N.C.)
Digital Input 2	\rightarrow Switch Home Y (N.C.)
Digital Input 3	→ Switch Home Z (N.C.)
Digital Input 4	\rightarrow GENERAL EMERGENCY INPUT (N.C.)
Digital Input 5	\rightarrow Button JOG X+ (N.O.)
Digital Input 6	\rightarrow Button JOG X- (N.O.)
Digital Input 7	\rightarrow Button JOG Y+ (N.O.)
Digital Input 8	\rightarrow Button JOG Y- (N.O.)
Digital Input 9	\rightarrow Button JOG Z+ (N.O.)
Digital Input 10	\rightarrow Button JOG Z- (N.O.)

Analog Inputs

Analog Inputs 1

→ Feed Potentiometer Override Axes

For enable this Override, you must select the Enable the "Ext OW" from IsoNs Interface"

JOG -		JOG +
0	😑 Inc Jog	0
C	😝 Ext OW	

Digital Outputs

Digital outputs 1	→ X axis enabled
Digital outputs 2	→ Y axis enabled
Digital outputs 3	→ Z axis enabled
Digital outputs 4	\rightarrow CNC Error

Axes Outputs

Step/Dir Ch 1	$\rightarrow x$
Step/Dir Ch 2	\rightarrow Y
Step/Dir Ch 3	→z

1) Open new project VTB and select NGQ hardware or NGM EVO (the example is on NGQ) Select 4 Ms sample



2) Set link on COM1(or COM2) NGQ-NGM EVO and PP Interp mask on 7 (X Y Z channel enabled)



3) Insert object ISOVIRTUAL and set the default properties $Objects \rightarrow Iso_Ns \rightarrow IsoVirtual.vco$



4) Insert Axis X ISOPP (The NGM EVO object is the same of the NGQ)

 $\textit{Objects} \rightarrow \textit{Iso}_\textit{Ns} \rightarrow \textit{IsoPP.vco}$



5) Set the following properties



6) Insert Axis Y ISOPP and set the following properties *Objects* \rightarrow *IsoNs* \rightarrow *IsoPP.vco*



7) Insert Axis Z ISOPP and set the following properties

 $Objects \rightarrow Iso_Ns \rightarrow IsoPP.vco$



9) Insert the object ObjInterpola Objects → Motor Control → CobjInterpola.vco







		-				
	Interpola1					
	Property	Event	s			
	Property		Value			
	Nome		Interp	oola	1	
	Left		65			
_	Тор		110			
	N.assi		3			
	N.tratti		16			
	Vper		1024			
	Div. Vper		1024			
	Abilita arcto		1	7		
~			_			

11) Insert in the Task main (or task plc) the code management

Init Task PLC Task PLC		
1	7	
2	' Read The Analog Inputs	
3	' For override control	
4	/	
5	ISOV1_vper=ng_adc(0)	
6	·	
7	' Test Digital Inputs	
8	۲	
9	ISOV1_ext_fcz_x=!ISOV1.inp0 ' Homing switch X	
10	ISOV1_ext_fcz_y=!ISOV1.inp1 ' Homing switch Y	
11	ISOV1_ext_fcz_z=!ISOV1.inp2 ' Homing switch Z	
12	ISOV1_ext_emcy=!ISOV1.inp3 ' General emergency	
13	ISOV1_ext_jogp_x=ISOV1.inp4 ' JOG X +	
14	ISOV1_ext_jogm_x=ISOV1.inp5 ' JOG X -	
15	ISOV1_ext_jogp_y=ISOV1.inp6 ' JOG Y +	
16	ISOV1_ext_jogm_y=ISOV1.inp7 ' JOG Y -	
17	ISOV1_ext_jogp_z=ISOV1.inp8 ' JOG Z +	
18	ISOV1_ext_jogm_z=ISOV1.inp9 ' <i>JOG Z</i> -	
19	·	
20	' Test Digital Outputs	
21	·	
22	ISOV1.out0=ISOV1_status_enable_x 'X enabled	
23	ISOV1.out1=ISOV1_status_enable_y 'Y enabled	
24	ISOV1.out2=ISOV1_status_enable_z 'Z enabled	
25	ISOV1.out2=ISOV1_status_error ' CNC error	

·_____

' Read The Analog Inputs

' For override control

ISOV1_vper=ng_adc(0)

' Test Digital Inputs

'___

r

ISOV1_ext_fcz_x=!ISOV1.inp0	' Homing switch X
ISOV1_ext_fcz_y=!ISOV1.inp1	' Homing switch Y
ISOV1_ext_fcz_z=!ISOV1.inp2	' Homing switch Z
ISOV1_ext_emcy=!ISOV1.inp3	' General emergency
ISOV1_ext_jogp_x=ISOV1.inp4	' JOG X +
ISOV1_ext_jogm_x=ISOV1.inp5	' JOG X -
ISOV1_ext_jogp_y=ISOV1.inp6	' JOG Y +
ISOV1_ext_jogm_y=ISOV1.inp7	' JOG Y -
ISOV1_ext_jogp_z=ISOV1.inp8	' JOG Z +
ISOV1_ext_jogm_z=ISOV1.inp9	' JOG Z -
 '	

' Test Digital Outputs

!	
ISOV1.out0=ISOV1_status_enable_x	' X enabled
ISOV1.out1=ISOV1_status_enable_y	' Y enabled
ISOV1.out2=ISOV1_status_enable_z	' Z enabled
ISOV1.out2=ISOV1_status_error 'CNC e	error

14.2 NG35+2xNGIO Axes 3 Analog +/- 10V and handwheel

Link ETHERNET IP: "10.0.0.80" (default)

The follwing project used a handwell connected to Ch 2 second NGIO encoder inputs , selector for JOG AXES and spindle.

To enable a selector is necessary inserti in the init TASK PLC the following code:

ISOV1_soft_sel_man=0 'Enable the internal VTB selector

Digital Inputs

Digital Input 1	→ Switch Home X (N.C.)
Digital Input 2	→ Switch Home Y (N.C.)
Digital Input 3	→ Switch Home Z (N.C.)
Digital Input 4	→ GENERAL EMERGENCY INPUT (N.C.)
Digital Input 5	→ Selector JOG X (N.O.)
Digital Input 6	→ Selector JOG Y (N.O.)
Digital Input 7	→ Selector JOG Z (N.O.)
Digital Input 8	→ Button JOG - (N.O.)
Digital Input 9	→ Button JOG + (N.O.)
Digital Input 10	→ Handwheel Speed x1
Digital Input 11	→ Handwheel Speed x10
Digital Input 12	→ Handwheel Speed x100

Analog Inputs

 \rightarrow X encoder feedback

 \rightarrow Y encoder feedback

 \rightarrow Z encoder feedback

→ HandWheel encoder

	JOG +
Inc Jog	0
🗑 Ext OW	0
	 Inc Jog Ext OW

Digital Outputs

Digital outputs 1	→ X axis enabled
Digital outputs 2	\rightarrow Y axis enabled
Digital outputs 3	\rightarrow Z axis enabled
Digital outputs 4	\rightarrow CNC Error
Digital outputs 5	→ Spindle start/stop
Digital outputs 6	→ Spindle CW (M3)
Digital outputs 7	\rightarrow Spindle CCW (M4)

Axes Inputs

Encoder Ch 1 (first NGIO) Encoder Ch 2 (first NGIO) Encoder Ch 1 (second NGIO) Encoder Ch 2 (second NGIO)

Axes Outputs

→ X Speed +/-10V
→ Y Speed +/-10V
→ Z Speed +/-10V
\rightarrow SPEED Spindle

1) Open new project VTB and select NG35 Select 1 Ms sample

Start Page:	1	
Sample:	1	mS
Task Time: 5	x 1 =	5 mS
Screensave:	🔽 Enable	30 sec

2) Insert object ISOVIRTUAL and set the default properties

$\textit{Objects} \rightarrow \textit{Iso}_\textit{Ns} \rightarrow \textit{IsoVirtual.vco}$



3) Insert Axis X ISOPID Objects → Iso_Ns → IsoPid.vco



4) Set the following properties

		PID1	
Main []		Property Even	ts
		Property	Value
	~	Nome	PID1
GIXI00 ISO		Left	60
		Тор	10
	(Indice asse ISO	
		Nome processo	ISOV1
		Indice asse NG-IO	0

5) Insert Axis Y ISOPID and set the following properties

 $Objects \rightarrow Iso_Ns \rightarrow IsoPid.vco$



6) Insert Axis Z ISOPID and set the following properties *Objects* → *Iso_Ns* → *IsoPid.vco*





	PID3		
	Property Events		
	Property	Value	
	Nome	PID3	
	Left	10	
	Тор	55	
	Indice asse ISO	2	
(Nome processo	ISOV1	
$\mathbf{\nabla}$	Indice asse NG-IO	1	

7) Insert the object ObjInterpola Objects → Motor Control → CobjInterpola.vco



8) Set the following properties



9) Declare a following Global Variables

Internal VAR Bi	it VAR Defi	ne Static VAR	v	SD VAR	Fixed V/
			No 🔻	EXP	
Variable	Type	S	hared	Export in Class	
EncoderInput	LONG	N	lo lo		
EncoderOut	LONG	N	lo		

10) Insert the FiltroVol Object for handwheel *Objects* → *Motor Control* → *CfiltroVol.vco*



11) Set the following properties



12) Insert in "Init task PLC " the entry point for M Functions and the enable external selector

	TASK	PLC Code
	Ind. T.	ssk PLC Task PLC
l	1	ISOV1_soft_sel_man=0 ' Enable the internal VTB selector
	2	ISOV1_Start_m=StartMacro ' entry point MACRO management

13) Insert 2 Define Constant in Global Variables → Define

The MAXSPEEDSPINDLE depend to MAX rpm at 10 Volt your spindle

	Internal VAR	Bit VAR	Define	Static VAR
l	Variable		Туре	
L	MAXDAC			2047
L	MAXSPEEDSPINDLE			24000

14) Insert in Task Main Functions Page M functions management

F	Page Init	Master Event	Master Cycle	Page Functions
1	function	StartMacro() as char	
2	dim Vels	Spindle as lo	ng	
3				
4	ISOV	/1_m_ACK=1		
5	sele	ct ISOV1_M_c	md	
6		case 3		' start spindle in CW
7		ISOV1.ou	t5=true	' set CW mode
8		ISOV1.ou	t6=false	' reset CCW mode
9		' calcul	ate the Speed	d
10		VelSpind	le=(ISOV1_gen	neric(9)*MAXDAC)/MAXSPEEDSPINDLE
11		ng_dac(3	,VelSpindle)	' Update the Speed on Dac out
12		ISOV1.ou	t4=true	' Start spindle
13		ISOV1_st	atus_m_run=0	
14		case 4		' start spindle in CCW
15		ISOV1.ou	t5=false	' reset CW mode
16		ISOV1.ou	t6=true	' set CCW mode
17		' calcul	ate the Speed	d
18		VelSpind	le=(ISOV1_ge	neric(9)*MAXDAC)/MAXSPEEDSPINDLE
19		ng_dac(3	,VelSpindle)	' Update the Speed on Dac out
20		ISOV1.ou	t4=true	' Start spindle
21		ISOV1_st	atus_m_run=0	
22		case 5		' Stop spindle
23		ISOV1.ou	t4=false	' Stop spindle
24		VelSpind	le=0	' set Speed to 0
25		ng_dac(3	,VelSpindle)	' Update the Speed on Dac out
26		ISOV1_st	atus_m_run=0	
27		case else		
28		ISOV1_m_	ACK=0	
29	ends	select		
30	endfunct	tion		

function StartMacro() as char dim VelSpindle as long

```
ISOV1_m_ACK=1
       select ISOV1_M_cmd
               case 3
                                               ' start spindle in CW
                       ISOV1.out5=true
                                               'set CW mode
                       ISOV1.out6=false
                                                       ' reset CCW mode
                       ' calculate the Speed
                       VelSpindle=(ISOV1_generic(9)*MAXDAC)/MAXSPEEDSPINDLE
                                               ' Update the Speed on Dac out
                       ng_dac(3,VelSpindle)
                                                       'Start spindle
                       ISOV1.out4=true
                       ISOV1_status_m_run=0
               case 4
                                               ' start spindle in CCW
                                                       ' reset CW mode
                       ISOV1.out5=false
                       ISOV1.out6=true
                                                       ' set CCW mode
                       ' calculate the Speed
                       VelSpindle=(ISOV1_generic(9)*MAXDAC)/MAXSPEEDSPINDLE
                       ng dac(3,VelSpindle)
                                               ' Update the Speed on Dac out
                       ISOV1.out4=true
                                                       'Start spindle
                       ISOV1_status_m_run=0
                                               ' Stop spindle
               case 5
                       ISOV1.out4=false
                                                       ' Stop spindle
                       VelSpindle=0
                                               'set Speed to 0
                       ng_dac(3,VelSpindle)
                                               ' Update the Speed on Dac out
                       ISOV1_status_m_run=0
               case else
                       ISOV1_m_ACK=0
       endselect
endfunction
```

15) Insert in Task Main (Master Cycle) Or Task PLC the Call at Functions for I/O Management

Pa	age Init	Master Event	Master Cycle Page Functions
1	Assi	Homing()	' Control homing Switch
2	GetE	MCY()	' Get EMERGENCY status
3	Assi	ManualJog()	' Control Manual JOG
4	Spee	dHeWheel()	' Control Speed HandWheel
5	Get0	verride()	' Read the Override potentiometer
6	Set0	utputs()	' Set Digital outputs

AxesHoming()	' Control homing Switch
GetEMCY()	' Get EMERGENCY status
AxesManualJog()	' Control Manuale JOG
SpeedHandWheel()	' Control Speed HandWheel
GetOverride()	' Read the Override potentiometer
SetOutputs()	' Set Digital outputs

16) Insert the functions in Task Main (Page Functions)

<pre>1 ''''''''''''''''''''''''''''''''''''</pre>		Pa	age Init	Master Event	Master Cycle	Page Functions	
<pre>2 ' Control the switch Axes homing 3 '************************************</pre>		1	******	******	********	**	
<pre>3</pre>		2	' Contro	l the switch	Axes homing		
<pre>indiction Accessing() ext_fcz_v=!ISoV1.inp0 ' Homing switch X isoV1_ext_fcz_v=!ISoV1.inp1 ' Homing switch Y isoV1_ext_fcz_z=!ISoV1.inp2 ' Homing switch Z endfunction ''</pre>		3 4	*******	***********	**************************************	**	
<pre>6 ISOV1_ext_fcz_y=!ISOV1.inp1 ' Homing switch Y 7 ISOV1_ext_fcz_z=!ISOV1.inp2 ' Homing switch Z 8 endfunction 9 . 10 . 11 . '************************************</pre>		5	ISOV	1 ext fcz x=	ISOV1.inp0	' Homing swit	ch X
<pre>7 ISOV1_ext_fcz_z=!ISOV1.inp2 ' Homing switch 2 8 endfunction 9 . 10 . 11 . '************************************</pre>		6	ISOV	1 ext fcz y=	!ISOV1.inp1	' Homing swit	ch Y
<pre>8 endfunction 9 10 10 11 . ''Control the switch Axes homing ' function AxesHoming() as void</pre>		7	ISOV	1_ext_fcz_z=	!ISOV1.inp2	' Homing swit	ch Z
<pre> 10 10 11 1 'Control the switch Axes homing function AxesHoming() as void</pre>		8	endfunct	ion			
'Control the switch Axes homing '		9	•				
<pre>'************************************</pre>		11	:				
<pre>''Control the switch Axes homing ''Control the switch Axes homing '' function AxesHoming() as void</pre>							
' Control the switch Axes homing function AxesHoming() as void ISOV1_ext_fcz_x=!ISOV1.inp0 ' Homing switch X ISOV1_ext_fcz_y=!ISOV1.inp1 ' Homing switch Z endfunction ' Control the General Emergency ' Control the General Emergency i SOV1_ext_emcy=!ISOV1.inp3 ' General emergency endfunction ' Control Manuale JOG ' Control Manuale JOG ' fISOV1.inp4 ' Set Axis X ISOV1_asse_man=0 endif if ISOV1.inp5 ' Set Axis Y	*****	*****	******	*****	****		
<pre>'****** function AxesHoming() as void</pre>	Contra	al tha	owitch As	oc homing			
function AxesHoming() as void ISOV1_ext_fcz_x=!ISOV1.inp0 'Homing switch X ISOV1_ext_fcz_y=!ISOV1.inp1 'Homing switch Y ISOV1_ext_fcz_z=!ISOV1.inp2 'Homing switch Z endfunction '************************************	Lonuro	or the	SWILCH A)	es noming	****		
ISOV1_ext_fcz_x=!ISOV1.inp0 'Homing switch X ISOV1_ext_fcz_y=!ISOV1.inp1 'Homing switch Y ISOV1_ext_fcz_z=!ISOV1.inp2 'Homing switch Z endfunction '************************************				N = =			
ISOV1_ext_fcz_x=!ISOV1.inp0 'Homing switch X ISOV1_ext_fcz_y=!ISOV1.inp1 'Homing switch Y ISOV1_ext_fcz_z=!ISOV1.inp2 'Homing switch Z endfunction '************************************	τυπςτιο	n Axe	sHoming() as void			
ISOV1_ext_fcz_y=!ISOV1.inp1 'Homing switch Y ISOV1_ext_fcz_z=!ISOV1.inp2 'Homing switch Z endfunction '************************************		ISOV	1_ext_fc	z_x=!ISOV1.in	p0 Homi	ng switch X	
ISOV1_ext_fcz_z=!ISOV1.inp2 'Homing switch Z endfunction '************************************		ISO\	1_ext_fc	z_y=!ISOV1.in	p1 'Homi	ng switch Y	
endfunction '************************************		ISO\	1_ext_fc	z_z=!ISOV1.in	p2 'Homi	ng switch Z	
<pre>'****** ' Control the General Emergency ' function GetEMCY() as void ISOV1_ext_emcy=!ISOV1.inp3 ' General emergency endfunction '****** ' Control Manuale JOG '***** function AxesManualJog() as void if ISOV1.inp4 ' Set Axis X ISOV1_asse_man=0 endif if ISOV1.inp5 ' Set Axis Y</pre>	endfun	ction					
' Control the General Emergency '************************************	*****	****	******	******	****		
<pre>'****** function GetEMCY() as void ISOV1_ext_emcy=!ISOV1.inp3 'General emergency endfunction '****** ' Control Manuale JOG '****** function AxesManualJog() as void if ISOV1.inp4 'Set Axis X ISOV1_asse_man=0 endif if ISOV1.inp5 'Set Axis Y</pre>	' Contro	ol the	General E	Emergency			
function GetEMCY() as void ISOV1_ext_emcy=!ISOV1.inp3 'General emergency endfunction 'Control Manuale JOG 'Control Manuale JOG function AxesManualJog() as void if ISOV1.inp4 'Set Axis X ISOV1_asse_man=0 endif if ISOV1.inp5 'Set Axis Y	*****	****	*****	*****	* * * *		
ISOV1_ext_emcy=!ISOV1.inp3 'General emergency endfunction '************************************	functio	n Get	EMCY() as	s void			
endfunction '************************************		ISO\	/1 ext er	ncv=!ISOV1.in	103 'Gener	ral emergency	
'*************************************	endfun	ction					
' Control Manuale JOG '************************************	*****	*****	******	*****	****		
function AxesManualJog() as void if ISOV1.inp4 'Set Axis X ISOV1_asse_man=0 endif if ISOV1.inp5 'Set Axis Y	' Contre						
function AxesManualJog() as void if ISOV1.inp4 'Set Axis X ISOV1_asse_man=0 endif if ISOV1.inp5 'Set Axis Y	*****	*****	*******	•	* * * *		
if ISOV1.inp4 'Set Axis X ISOV1_asse_man=0 endif if ISOV1.inp5 'Set Axis Y	functio		- Manual I				
ISOV1.inp4 Set Axis X ISOV1_asse_man=0 endif if ISOV1.inp5 'Set Axis Y	Tunctio	n Axe		og() as void			
ISOV1_asse_man=0 endif if ISOV1.inp5 'Set Axis Y		11 150	JV1.inp4		Set Axis X		
endif if ISOV1.inp5 'Set Axis Y			ISOV	1_asse_man=	0		
if ISOV1.inp5 'Set Axis Y		endi	f				
		if ISC	OV1.inp5	10	Set Axis Y		
ISOV1_asse_man=1			ISOV	1_asse_man=	1		
endif		endi	f				
if ISOV1.inp6 'Set Axis Z		if ISC	OV1.inp6	'S	et Axis Z		
ISOV1 asse man=2			ISOV	1 asse man=	2		

endif ISOV1_ext_jogp=ISOV1.in ISOV1_ext_jogm=ISOV1.in endfunction	58 'Update the Jog Input + 1 p7 'Update the Jog Input -
Control Manuale JOG	
' The update Encoder is in Task PLC	****
function SpeedHandWheel() as voi	d
if ISOV1.inp9	multiplier x1
ISOV1_msofv=1	
endif	
if ISOV1.inp10	multiplier x10
ISOV1_msofv=10	
endit	
if ISOV1.inp11	multiplier x100
ISOV1_MSOTV=100)
endfunction	
!**************************************	****
' Control Override potentiometer	****
function GetOverride()as void	
ISOV1_vper=ng_adc(0)	
endfunction	
***************************************	****
' Set digital outputs '************************************	****
function SetOutputs()as void	
ISOV1.out0=ISOV1_status	_enable_x 'X enabled
ISOV1.out1=ISOV1_status	_enable_y 'Y enabled
ISOV1.out2=ISOV1_status	_enable_z 'Z enabled
ISOV1.out3=ISOV1_status	_error 'CNC error
enarunction	

17) Insert in theTask PLC the handwheel encoder update This functions must be sync with task PLC

TA	SK PLC Code	
Init	Task PLC Task PLC	
1	ng_enc(3,EncoderInput())	' read the HandWheel encoder
2	ISOV1_qvola=EncoderOut	'Update the Handwheel from FiltroVol Object

ng_enc(3,EncoderInput()) ISOV1_qvola=EncoderOut 'read the HandWheel encoder 'Update the Handwheel from FiltroVol Object

14.3 NG35+1xNGIO Axes 3 CanOpen

Link ETHERNET IP: "10.0.0.80" (default) The follwing project used a axes Canopen type ESTUN

Digital Inputs

Digital Input 1	→ Switch Home X (N.C.)
Digital Input 2	→ Switch Home Y (N.C.)
Digital Input 3	→ Switch Home Z (N.C.)
Digital Input 4	→ GENERAL EMERGENCY INPUT (N.C.)

Digital Input 5	\rightarrow Button JOG X+ (N.O.)
Digital Input 6	\rightarrow Button JOG X- (N.O.)
Digital Input 7	\rightarrow Button JOG Y+ (N.O.)
Digital Input 8	\rightarrow Button JOG Y- (N.O.)
Digital Input 9	\rightarrow Button JOG Z+ (N.O.)
Digital Input 10	\rightarrow Button JOG Z (N.O.)

Analog Inputs

Analog Inputs 1 → Feed Potentiometer Override Axes For enable this Override, you must select the Enable the "Ext OW" from IsoNs Interface"



Digital Outputs

Digital outputs 1 Digital outputs 2 Digital outputs 3 Digital outputs 4 → X axis enbled
 → Y axis enbled
 → Z axis enbled
 → CNC Error

1) Open new project VTB and select NG35 – Enable the CanOpen Fieldbus – see following

Option				x
General RS232 Pro	otocol Field Bus	Protocol	Hardware Conf.	Connection
CAN OPEN Protocol		ETHERO	CAT Protocol	
CAN OPEN	–	- nessu	uno -	_
Baud rate Sync				
500000 Off C	On 🔎			
CAN error showing mode				
None	0			
Standard	0			
Custom	e			
-Slow Px				
0 @ 1 C 2 C				
			ОК	Annulla

Select a 2 Ms sample

Start Page:	1
Sample:	2,0 mS
Task Time: 5	x 2,0 = 10 mS
Screensave:	▼ Enable 30 sec

2) Prepare the file COP with CanOpen configurator A) Open the CanOpen configurator



Promax - Configuratore reti CanOpen File Modifica Opzioni Libreria Help	×
	Prodotti Can presenti : 0 Dati Pdo Modo Byte Cob_Id Com Inhibit_time Event_time RTB Oggett Mappati

B) Add from Lib the estun type and insert node 1 – Press button "esegui" Repeat for Node 2 and Node 3

) Inserisci nodo	
÷	CiA DS402.eds
🖶 🗁 Axor	PRONET/ED
🖷 🗁 Baumuller	- PDO Quota r
🖮 🗁 CiA_DS402	- PDO Quota i
🖶 🗁 Danaher	
🖕 🗁 Estun	*** Campionam
Estun.libs	
🖕 🗁 Hengstler	
🛓 🗁 Lust	
🖕 🗁 Parker	
🖕 🗁 Phase	
Dramau	

Baumuller CiA_DS402 Danaher Estun Estun.libs HDT Hengstler Lust Parker Phase Schneider Vipa	PRONET/EDC configurato con: - FDO Quota reale (qa) - FDO Quota interpolata (qx) *** Campionamento impostato a 2mSec
	Inserisci al nodo Inserisci al nodo Image: Salva Chiudi

X

Modifica Opzioni Libreria He	slp
🗃 🖬 🔋 👪 🖿 🐰	B 🛍 👬
xes (modificato)	
⊞CiA_DS402 (1)	
Ė CiA_DS402 (2)	
н CiA DS402 (3)	

C) Expand node 2 and double click on pdo_Tx1 (Fast)

😋 Configura Pdo	
Pdo Mappature	
0k 🗢 🗅 🕂 🐰 🔟	
Prodotto : CiA_DS402 (2	2)
Process data object : TX 1	
Modo Fast Tast Tast Tast	
Rute T	

D) Double click on qa(32)

Mappatura	
0k 🗾	
Prodotto	
Pdo	
Numero mappatura	1
Name Procession	1

Delete all text Name – (6064 sub0) qa And Insert only text Qb and press button Ok

🔄 Aggiu	ungi mappatura pe	r
Mappat	ura	
Ok 🕫		
Prodo	tto	CiA_DS402
Pdo		TX 1
Nume	ro mappatura	1
Name	qb	•
Index	6064	Subindex 0
Valuta	index in base sadecimale ecimale	Lenght 32

E) Double clik on pdo_Rx1 (fast)

🖪 Configura Pdo	
Pdo Mappature	
0k 💌 🗋 🕂 🐰 🔟	
Prodotto : CiA DS402 ((2)
Process data object : RX 1	
Modo Fast	
Byte 4	

F) Double click on qx(32)

Mappatura	
0k 🕫	
Prodotto	CiA_DS402
Pdo	RX 1
Numero mappatura	1

Delete all text Name – (60C1 sub1) qx And Insert only text Qy and press button Ok

Mannati	(in		
	ura		
Prodot	to	CiA D	S402
Pdo		RX	
Nume	ro mappatura		1
Name	Qy		•
Index	60C1	Subindex 1	
Valuta E	index in base sadecimale	Lenght 32	

G) Press Ok for enable the modify

😋 Configura Pdo	
Pdo Mappature	
ок 🗠 🗅 🕂 🐰 🔟	
Prodotto : CiA_DS402 (2)	
Process data object : RX 1	
Modo Fast	

Repeat point C to G for node 3 Inserting Qc(Qb) and Qz(Qy)

H) Press Save for save configuration



Now the CanOpen Axes configuration is Ready. The CanOpen Drives must be set in the following mode:

X AXIS	Node 1	Baud 500 Kb
Y AXIS	Node 2	Baud 500 Kb
Z AXIS	Node 3	Baud 500 Kb

3) Insert object ISOVIRTUAL and set the default properties *Objects* → *Iso_Ns* → *IsoVirtual.vco*



4) Insert Axis X ISOCanOpen Objects → Iso_Ns → IsoCanOpen.vco





Note:

For select the PDO QX,QY and QZ, you must have first created the configuration CanOpen. When you Double Click on "Nome quota pdo", the windows Variable List is open. Select the VCB tab and choose the variable name with double click

Internal	Bit	VCB	System	Define	Static	Fixed	VSD
Jame			1	Type			
IX				LONG	2		
iy Iy				LONG			-
ļΖ				LONG			
							-
· · · · ·							

6) Insert Axis Y ISOCanOpen and set the following properties *Objects* → *Iso_Ns* → *IsoCanOpen.vco*



7) Insert Axis Z ISOCanOpen and set the following properties *Objects* → *Iso_Ns* → *IsoCanOpen.vco*



8) Insert the object ObjInterpola Objects → Motor Control → CobjInterpola.vco





10) Insert in the Task main (or task plc) the code management

TASK PLC Code		
Init Task PLC Task PLC		
1	7	
2	' Read The Analog Inputs	
3	' For override control	
4	/	
5	ISOV1 vper=ng adc(0)	
6	·	
7	' Test Digital Inputs	
8	/	
9	ISOV1 ext fcz x=!ISOV1.inp0 ' Homing switch X	
10	ISOV1 ext fcz y=!ISOV1.inp1 ' Homing switch Y	
11	ISOV1_ext_fcz_z=!ISOV1.inp2 ' Homing switch Z	
12	ISOV1_ext_emcy=!ISOV1.inp3 ' General EMERGENCY	
13	ISOV1_ext_jogp_x=ISOV1.inp4 ' JOG X +	
14	ISOV1_ext_jogm_x=ISOV1.inp5 ' JOG X -	
15	ISOV1_ext_jogp_y=ISOV1.inp6 ' JOG Y +	
16	ISOV1_ext_jogm_y=ISOV1.inp7 ' JOG Y -	
17	ISOV1_ext_jogp_z=ISOV1.inp8 ' JOG Z +	
18	ISOV1_ext_jogm_z=ISOV1.inp9 ' JOG Z -	
19	·	
20	' Test Digital Outputs	
21	·	
22	ISOV1.out0=ISOV1_status_enable_x 'X enabled	
23	ISOV1.out1=ISOV1_status_enable_y 'Y enabled	
24	ISOV1.out2=ISOV1_status_enable_z 'Z enabled	
25	ISOV1.out2=ISOV1_status_error ' CNC error	

·_____

' Read The Analog Inputs

' For override control

ISOV1_vper=ng_adc(0)

' Test Digital Inputs

'___

ī

ISOV1_ext_fcz_x=!ISOV1.inp0	' Homing switch X
ISOV1_ext_fcz_y=!ISOV1.inp1	' Homing switch Y
ISOV1_ext_fcz_z=!ISOV1.inp2	' Homing switch Z
ISOV1_ext_emcy=!ISOV1.inp3	' General EMERGENCY
ISOV1_ext_jogp_x=ISOV1.inp4	'JOG X +
ISOV1_ext_jogm_x=ISOV1.inp5	' JOG X -
ISOV1_ext_jogp_y=ISOV1.inp6	'JOG Y +
ISOV1_ext_jogm_y=ISOV1.inp7	' JOG Y -
ISOV1_ext_jogp_z=ISOV1.inp8	' JOG Z +
ISOV1_ext_jogm_z=ISOV1.inp9	' JOG Z -
l	

' Test Digital Outputs

·	
ISOV1.out0=ISOV1_status_enable_x	' X enabled
ISOV1.out1=ISOV1_status_enable_y	' Y enabled
ISOV1.out2=ISOV1_status_enable_z	' Z enabled
ISOV1.out2=ISOV1_status_error 'CNC	error

14.4 NGM EVO+NGQx (CanOpen) Axes 3 Step/Dir, Spindle and handwheel

Link RS32 on COM1 NGM EVO

The following project use a handwheel connect to Ch 1 encoder inputs NGQx , selector for JOG AXES and spindle in Analog output 1 in NGQx. The selector Axes JOG and Handwheel speed are connect to NGQx digital inputs in CanOpen To enable a selector is necessary insert in the init TASK PLC the following code: ISOV1_soft_sel_man=0 'Enable the internal VTB selector

Digital Inputs

Digital Input 1	(NGM EVO <i>ISOV1.inp0</i>)	→ Switch Home X (N.C.)
Digital Input 2	(NGM EVO <i>ISOV1.inp1</i>)	→ Switch Home Y (N.C.)
Digital Input 3	(NGM EVO <i>ISOV1.inp2</i>)	→ Switch Home Z (N.C.)
Digital Input 4	(NGM EVO <i>ISOV1.inp3</i>)	→ GENERAL EMERGENCY INPUT (N.C.)
•		
•		
Digital Input 1	(NGQx ISOV1.inp16)	→ Selector JOG X (N.O.)
Digital Input 2	(NGQx ISOV1.inp17)	→ Selector JOG Y (N.O.)
Digital Input 3	(NGQx ISOV1.inp18)	→ Selector JOG Z (N.O.)
Digital Input 4	(NGQx ISOV1.inhp19)	→ Button JOG - (N.O.)
Digital Input 5	(NGQx ISOV1.inp20)	→ Button JOG + (N.O.)
Digital Input 6	(NGQx ISOV1.inp21)	→ Handwheel Speed x1
Digital Input 7	(NGQx ISOV1.inp22)	→ Handwheel Speed x10
Digital Input 8	(NGQx ISOV1.inp23)	→ Handwheel Speed x100

Analog Inputs

Analog Inputs 1 (NGQx) \rightarrow Feed Potentiometer Override Axes For enable this Override, you must select the Enable the "Ext OW" from IsoNs Interface"



Digital Outputs

Digital outputs 1 (NGM EVO ISOV1.out0)
Digital outputs 2 (NGM EVO ISOV1.out1)
Digital outputs 3 (NGM EVO ISOV1.out2)
Digital outputs 4 (NGM EVO ISOV1.out3)

Digital outputs 1 (NGQx *ISOV1.out16*) Digital outputs 2 (NGQx *ISOV1.out17*) Digital outputs 3 (NGQx *ISOV1.out18*)

Encoder Inputs

Encoder Ch 1 (NGQx)

Analog Outputs

Analog out 1 (NGQx)

→ X axis enabled
 → Y axis enabled
 → Z axis enabled
 → CNC Error

- → Spindle start/stop
- → Spindle CW (M3)
- → Spindle CCW (M4)

→ HandWheel encoder

 \rightarrow SPEED Spindle

1) Open new project VTB and select NGM EVO – Enable the CanOpen Fieldbus – see following

Option		×
General RS232 Protocol Field Bus P	Protocol Hardware Conf.	Connection
CAN OPEN Protocol	ETHERCAT Protocol	
CAN OPEN 💌	- nessuno -	-
Baud rate Sync		
500000 Off C On @		
CAN error showing mode		
None C		
Standard C		
Custom (•		
Slow Px 0 @ 1 C 2 C		
	ОК	Annulla

Select a 4 Ms sample

Start Page:	1
Sample:	4 mS
Task Time: 5	x 4 = 20 mS
Screensave:	I Enable 30 sec

2) Prepare the file COP with CanOpen configurator

A) Open the CanOpen configurator



File Modifica Opzioni Libreria Help	
	Prodotti Can presenti : 0 Dati Pdo Mode Byte Cob_Id Comm Comm Comm Nictime RTR Oggetti Mappati

B) Add from Lib the Promax type Canax → CanAX2.libs and insert node 1 – Press button *"esegui"*



C) Press button Save



3) Set link on COM2 NGM EVO and PP Interp mask on 7 (X Y Z channel enabled)



4) Insert object ISOVIRTUAL and set the default properties

$\textit{Objects} \rightarrow \textit{Iso}_\textit{Ns} \rightarrow \textit{IsoVirtual.vco}$



5) Insert Axis X ISOPP Objects → Iso_Ns → IsoPP.vco





7) Insert Axis Y ISOPP and set the following properties *Objects* → *Iso_Ns* → *IsoPP.vco*



PP2	
Property Event	s
Property	Value
Nome	PP2
Left	65
Тор	60
Indice asse ISO	1
Nome processo	ISOV1
NGM-13 Channel	1

8) Insert Axis Z ISOPP and set the following properties $Objects \rightarrow Iso_Ns \rightarrow IsoPP.vco$



	PP3	
	Property Event	s
	Property	Value
	Nome	PP3
	Left	115
	Тор	88
1	Indice asse ISO	2
L	Nome processo	ISOV1
N	NGM-13 Channel	2

9) Insert the ISO-IO Can-Ax (is the same of NGQx) $Objects \rightarrow Iso_Ns \rightarrow ISO-IO.vco$







digio1			
Property Eve	ents		
Property	Value		
Nome	digio 1		
Nodo	0		
Allarme cfg	41		
Nome processo	ISOV1		
Indice ISO-IO (16 bi	t) 1 5		
Hardware enable	True		
Variabile inp	Input1		
Variabile out	Output1		

Note:

For select the Variabile Inp and Variabile out, you must have first created the configuration CanOpen. When you Double Click on "Variabile Inp" or " Variabile out", the windows Variable List is open. Select the VCB tab and choose the variable name with double click

Internal Bit	VCB	System	Define	Static	Fixed	VSD
Name			Туре			-
Input1			INT	1		
EncX			LONG			
EncY			LONG			
AnaInput			INT			
Output1			CHAR			
AnaOut1			INT			
AnaOut2			INT			
					1	1
Name Input1					ок	Close

11) Insert the object ObjInterpola

 $Objects \rightarrow Motor \ Control \rightarrow CobjInterpola.vco$





13) Declare a following Global Variables

Internal VAR Bit VAR	Define	Static VAR	VSD VAR	Fixed VA
		▼ No	▼ EXP	
Variable	Туре	Shar	ed Export in Cl	ass
EncoderInput	LONG	No		
EncoderOut	LONG	No		

14) Insert the FiltroVol Object for handwheel Objects → Motor Control → CfiltroVol.vco



15) Set the following properties

		FiltroVol1				
Main II		Property Even	ts			
Main []		Property	Value			
		Nome	FiltroVol 1			
		Left	100			
		Тор	55			
STEP.DIR STEP.DIR CAN-AX	/	Numero elementi	10			
	(Molt. filtro	100			
	(Encoder	EncoderInput			
OB1 CB1		Variabile	EncoderOut			

16) Insert in "Init task PLC " the entry point for M Functions and the enable external selector

	TASK	PLC Cod	e					
	Ind. T.	ask PLC	Task PLC					
l	1	ISOV1	soft_sel	_man=0	' Enable	the in	ternal VTB	selector
l	2	ISOV1	Start_m=	StartMacro	' entry	point .	MACRO manag	gement

17) Insert 2 Define Constant in Global Variables → Define

The MAXSPEEDSPINDLE depend to MAX rpm at 10 Volt your spindle

Internal VAR	Bit VAR	Define	Static VAR
Variable		Туре	
MAXDAC			2047
MAXSPEEDSPINDLE			24000

18) Insert in Task Main Functions Page M functions management



function StartMacro() as char dim VelSpindle as long

```
ISOV1_m_ACK=1
select ISOV1_M_cmd
                                       ' start spindle in CW
       case 3
                                               'set CW mode
                ISOV1.out17=true
               ISOV1.out18=false
                                               ' reset CCW mode
                ' calculate the Speed
                VelSpindle=(ISOV1_generic(9)*MAXDAC)/MAXSPEEDSPINDLE
                AnaOut1=VelSpindle
                                       ' Update the Speed on PDO
                                               'Start spindle
               ISOV1.out16=true
                ISOV1_status_m_run=0
       case 4
                                       ' start spindle in CCW
                                       ' reset CW mode
                ISOV1.out17=false
                ISOV1.out18=true
                                               'set CCW mode
                ' calculate the Speed
                VelSpindle=(ISOV1 generic(9)*MAXDAC)/MAXSPEEDSPINDLE
                AnaOut1=VelSpindle
                                       ' Update the Speed on PDO
                ISOV1.out16=true
                                               'Start spindle
                ISOV1_status_m_run=0
       case 5
                                        ' Stop spindle
                ISOV1.out16=false
                                       'Stop spindle
                VelSpindle=0
                                       ' set Speed to 0
                AnaOut1=VelSpindle
                                       ' Update the Speed on PDO
                ISOV1_status_m_run=0
       case else
                ISOV1_m_ACK=0
endselect
```

endfunction

19) Insert in Task Main (Master Cycle) Or Task PLC the Call at Functions for I/O Management

	Pa	Page Init Master Event		Master Cycle Page Functions
	1	AxesHomi	.ng ()	' Contro homing Switch
	2	GetEMCY ()	' Get emergency status
	3	AxesManu	alJog()	' Control Manuale JOG
ŀ	4	SpeedHan	dWheel()	' Control Speed handwheel
1	5	Get0verr	ide()	' Read the Override potentiometer
1	6	SetOutpu	its()	' Set Digital outputs

AxesHoming()	' Contro homing Switch
GetEMCY()	' Get emergency status
AxesManualJog()	' Control Manuale JOG
SpeedHandWheel()	' Control Speed handwheel
GetOverride()	' Read the Override potentiometer
SetOutputs()	' Set Digital outputs

20) Insert the functions in Task Main (Page Functions)

	Pa	age Init	Master Event	Master Cycl	e	Page Funct	acens	
	1	******	******	******	****	*		
	2	' Contro	l the switch	Axes hom:	ing			
	3	******	**********	*******	****	*		
	4	function	AxesHoming() as void		Remine		ch V
	6	TSOV	1_ext_1cz_x=	'ISOV1.in	50 ·	Homing	swit	ch X
	7	ISOV	1 ext fcz z=	!ISOV1.in	o2 '	Homing	swit	ch Z
	8	endfunct	ion	-				
	9							
	10	•						
	11	•						
*****	*****	*****	*****	****				
' Contro	ol the	switch A	kes homing					
!*****	*****	******	******	****				
functio	n Ave	sHoming) as void					
iunetio		/1 ovt fo	$y = \frac{1}{100}$	n0 'Ua	mir	a cwitch	v	
	1301		2_x=:150v1.in	ро по •1 Ци		ig switch	$\hat{\mathbf{v}}$	
	1501		z_y=!ISOV1.In		omir	ig switch	<u> </u>	
	ISOV	/1_ext_fc	z_z=!ISOV1.in	p2 'Ho	omir	ng switch	z	
endfun	ction							
*****	*****	*****	*****	****				
' Contro	ol the	General E	Emergency					
!****	*****	******	*****	****				
functio	n Getl	EMCY() a	s void					
	ISON	/1 ext er	ncv=!ISOV1.in	m3 'Ge	ner	al emerg	encv	
ondfun	ction		11cy=.150 V 1111			ui cilici b	circy	
!*****	*****	*****	****	****				
Contr	oi iviai	nuale JOG						
*****	****	* * * * * * * * *	* * * * * * * * * * * *	* * * *				
functio	n Axe	sManualJ	og() as void					
	if ISC	OV1.inp1	5 ' :	Set Axis X				
		ISOV	1_asse_man=	0				
	endi	f	· <u> </u>					
	if ISC	OV1.inp1	7 '	Set Axis Y				
		1001	1 assa man-	1				
	: ام مر م	1300	T_asse_IIIdII-	1				
	endi							
	if ISC	OV1.inp18	8 'S	et Axis Z				
		ISOV	1_asse_man=	2				

endif						
ISOV1 ext jogp=ISOV1.inp20 'Update the Jog Input +						
ISOV1 ext jogm=ISOV1.inp19 'Update the Jog Input -						
endfunction						
*****	****					
' Control Manuale JOG						
' The update Encoder is in Task PLC						
!*********	****					
function SpeedHandWheel() as vo	id					
if ISOV1.inp21	'multiplier x1					
ISOV1_msofv=1						
endif						
if ISOV1.inp22	'multiplier x10					
ISOV1_msofv=10						
endif						
if ISOV1.inp23	'multiplier x100					
ISOV1_msofv=10	0					
endif						
endfunction						
***************************************	*****					
Control Override potentiometer						
' from PDO declare in configurator	CanOpen					
***************************************	*****					
function GetOverride()as void						
ISOV1_vper=AnalInput						
endfunction	****					
	* * * * *					
Set digital outputs	****					
	_enable_x X enabled					
	enable z 'Zenabled					
	error 'CNC error					
andfunction						
Churanetion						

21) Insert in the Task PLC the handwheel encoder update

This functions must be sync with task PLC



EncoderInput=EncX ISOV1_qvola=EncoderOut 'read the HandWheel encoder from NGQx PDO EncX 'Update the Handwheel from FiltroVol Object

Index

1	PREFACE	3
2	BASE COMPONENTS	3
2.1	Select Hardware	3
2.2	Insert Object <i>cobjinterpola</i>	3
2.3	Properties setting of objinterpola	4
2.4	Insert Object Iso Virtual	4
2.5	Properties setting of IsoVirtual	4
2.6	Insert a long fixed variable name fixed0	5
3	Insert the Axes type	5
4	Insert the I/O	10
5	USE the M functions to internal the CNC	11
5.1	Read the M parameters	12
5.2	Write the M parameters	12
5.3	M flags	13
5.4	Example M3 M4 M5 start/stop Spindle	14
6	Standard I/O	15
7	Status Word	22
8	PLC I/O management	23
8.1	Defined bit digital Inputs	23
8.2	Defined bit digital Outputs	23
9	FEED External Override	23
10	Electronic HandWheel	24
11	Machine Parameters	27
11.1	General Parameters	27
11.2	2 Axes X Parameters	28
11.3	3 Custom Parameters	29
12	Alarms bit mapped	30
13	CanOpen Alarms	31
14	Examples	32
14.1	NGQ-NGM EVO 3 Axes Step/Dir	32
14.2	2 NG35+2xNGIO Axes 3 Analog +/- 10V and handwheel	
14.3	3 NG35+1xNGIO Axes 3 CanOpen	42
14.4	NGM EVO+NGQx (CanOpen) Axes 3 Step/Dir, Spindle and handwheel	51